



Figure 62-12. Main Rotor Blade Skin — Repair (Sheet 1 of 2)

407MM_62_0008