



U.S. Department  
of Transportation

**Federal Aviation  
Administration**

**Transport Airplane Directorate  
Los Angeles Aircraft  
Certification Office**

3960 Paramount Boulevard  
Lakewood, California 90712-4137

January 18, 2008

Mr. Pete Riedl  
Robinson Helicopter Company  
2901 Airport Drive  
Torrance, California 90505-6115

Reference: AMOC request to the FAA received on January 17, 2008.

Dear Mr. Riedl,

Approval of Alternative Method Of Compliance (AMOC)  
for AD 2007-26-12

The FAA concurs that the preflight check required by paragraph (c) of the AD is not required provided the following actions are performed:

1. At every 100 hour or annual inspection, whichever occurs first, inspect the main rotor blade in accordance with paragraph (a) of the AD; and
2. Update the applicable "Pilot Operating Handbook and FAA Approved Rotorcraft Flight Manual" to include revisions dated 20 April 2007, and later revisions.

These actions provide an acceptable level of safety in accordance with paragraph (d) of this AD.

This AMOC may be copied and distributed to any interested party.

If you have any questions regarding this approval, please contact Mr. Fred Guerin at (562) 627-5232, or Mr. Eric Schrieber at (562) 627-5348.

Sincerely,

Kevin Hull  
Manager, Los Angeles Aircraft Certification Office